



JON M. HUNTSMAN, JR.  
Governor


GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
**March 29, 2011**

Reviewed: 

<b>Mine Name:</b> Eureka Rock	<b>Permit Number:</b> S/023/0094
<b>Operator Name:</b> Eureka Rock LLC	<b>Inspection Date:</b> March 24, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 10:00 -10:15 AM
<b>Other Participants:</b> None	<b>Mine Status:</b> ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

This was a routine inspection.

**Inspection Summary:**

The surety on for the mine is inadequate. The current amount ins \$15,300.00 and the surety needs to be increased to \$20,300.00 till 2012 or \$20,800 till 2014.

The site was not being worked at the time of the inspection. Photographs were taken to document the site.

There are rock overhangs on the highwall that must be removed.

**Conclusions and Recommendations:**

The surety amount needs to be updated. The Division has contacted the Operator about increasing the surety.

The Division should sent a Division directive to the Operator requiring that the bond be increased and remove the overhangs.



**Inspector's Signature** \_\_\_\_\_

WHW:

cc: (OPERATOR)

[Jerry\\_Mansfield@BLM.gov](mailto:Jerry_Mansfield@BLM.gov)

O:\M023-Juab\S0230094-EurekaRock\inspections\Insp03242011.doc







